

LOCKHEED AIRCRAFT CORPORATION		ENGINEERING STUDY <input type="checkbox"/>		LAC -190							
DATE 9 June 1964		AFFECTS: WSPO <input checked="" type="checkbox"/>		PROJECT <input checked="" type="checkbox"/>							
NAME OF MAJOR COMPONENT		PART OR LOWEST SUBASSEMBLY FUEL COUNTER		PART NO. & MODEL OR TYPE							
TITLE OF PROPOSAL : FUEL COUNTER IMPROVEMENT											
NATURE OF PROPOSAL: Remove the existing plastic lens from the BU103104, Fuel Counters and install the new Q507-3 Lense, Q507-2 Back-up Plate, and new Nameplate. A Service Bulletin will be issued to rework and reidentify counters for all ships.											
Spares to be returned to LAC for rework and reidentification at a rate convenient to VRAMA (Recommended 10 per month).											
REASON FOR PROPOSAL: Age deterioration of the existing plastic lenses has caused them to bow and rub on the counter drums thus causing "sticky" operation of the counter.											
ES	ESTIMATED COST AND TIME INVOLVED :										
	ADDITIONAL FUNDING REQUIRED :										
CP	ESTIMATED COST FOR KITS OR PARTS : EP-1922 Cust. #1										
	ADDITIONAL FUNDING REQUIRED : None										
ITEMS AFFECTED BY PROPOSAL :											
SAFETY	MISSION EFFEC- TIVENESS	PERFORM- ANCE	OPERATING PROCEDURE	INTER- CHANGE- ABILITY	WEIGHT OR WEIGHT & BALANCE	TOOLS & SUPPORT EQUIPMENT	MAINTE- NANCE PROCEDURE	SERVICE LIFE	FLIGHT MANUAL	MAINTE- NANCE MANUAL	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
EST. MAN/HR. REQ'D. TO ACCOMPLISH CHANGE IN FIELD											
SOURCE OF PARTS FOR KIT LAC						AVAILABILITY 5 WEEKS AFTER APPROVAL for KITS SPARE Parts - Per COST. REQUIREMENTS					
DISPOSITION OF SPARES AFFECTED All BU103104 Counters to be modified and Reidentified.											
INITIATED BY :						APPROVED : WSPO					
Approved For Release 2002/08/21 : CIA-RDP89B00980R000200170022-1						STAT					